

Backlog of Essential Maintenance, Alterations, and Repairs (BEMAR)

Official 2007 Data
As of 10/1/2007

Deficiency Description	AB	AK	AQ	BE	BI	CA	NV	NS	OK	PH	PO	TU	Total
1 Public Law													
Life Safety Compliance	4,977,173	6,175,417	265,229	360,945	188,517	395,692	122,410	380,049	1,772,640	846,335	114,662	257,573	15,856,642
General Safety	5,753,647	3,379,212	413,754	127,635	307,018	12,740	1,080,880	119,220	18,508	770,497	478,316	11,830	12,473,257
Environmental Compliance	2,453,582	9,322,230	1,324,249	113,303	62,400	21,600	452,214	140,770	1,512,513	511,290	905,680	5,351	16,825,182
Handicapped Compliance	4,725,089	3,487,092	120,796	1,121,530	289,224	577,400	2,087,523	237,293	1,030,601	1,162,399	479,989	149,863	15,468,799
Energy Conservation	4,278,494	3,238,436	1,111,035	322,582	461,506	211,139	2,788,721	345,872	2,626,691	1,717,921	268,810	137,050	17,508,257
Seismic Mitigation	0	10,121,525	5,273,531		70,652		21,846,318	6,487,950	698,300	23,725,127		11,699	68,235,102
Sub Total	22,187,985	35,723,911	8,508,594	2,045,995	1,379,318	1,218,572	28,378,065	7,711,154	7,659,253	28,733,569	2,247,457	573,366	146,367,239
2 Improvements													
Patient Care	2,849,175	4,009,757	1,285,960	495,257	394,884	49,997	81,757	131,074	1,828,482	1,316,366	323,599	120,092	12,886,400
Program Deficiencies	20,928,033	13,056,904	7,326,494	200,000	2,178,380	13,790	306,093	2,670,099	500,533	1,585,106	2,311,930	1,540	51,078,902
Sub Total	23,777,208	17,066,661	8,612,454	695,257	2,573,264	63,787	387,850	2,801,173	2,329,015	2,901,472	2,635,529	121,632	63,965,302
3 Maintenance & Repair													
Architectural M&R	10,002,979	1,894,550	52,900	121,912	1,122,294	16,500	744,155	186,821	51,704	2,300,766	1,104,483	164,712	17,763,777
Structural M&R	5,073,277	10,541,486	2,405,140	1,574,396	2,288,565	1,830,149	1,438,659	535,851	4,052,445	1,410,487	529,796	1,632,953	33,313,204
Mechanical M&R	15,257,483	9,532,785	1,510,616	2,127,349	1,613,291	950,057	4,249,439	882,132	8,890,348	6,190,498	979,611	2,607,963	54,791,573
Electrical M&R	1,814,673	1,965,502	758,793	328,800	810,349	346,679	1,169,963	353,530	2,265,364	6,362,095	195,281	199,961	16,570,993
Utilities M&R	1,162,333	3,061,143	486,170	20,097	415,360	15,618	2,216,245	88,119	243,226	120,227	29,707	1,489,270	9,347,514
Grounds M&R	4,860,189	2,305,871	537,042	616,898	1,848,623	264,727	3,169,307	303,431	1,581,103	1,542,738	249,075	1,615,326	18,894,329
Painting M&R		221,781	4,395	449,475	311,879	67,263	1,302,506	61,623	49,048	578,711	57,061	34,934	3,138,676
Roof M&R	2,095,299	102,538	1,607,264	132,125	244,890	164,702	187,652	300,545	2,400,515	316,559	210,393	15,099	7,777,581
Sub Total	40,266,233	29,625,656	7,362,320	5,371,053	8,655,250	3,655,694	14,477,927	2,712,052	19,533,753	18,822,082	3,355,408	7,760,219	161,597,646
Grand Total													
Total	86,231,426	82,416,229	24,483,368	8,112,305	12,607,832	4,938,053	43,243,842	13,224,379	29,522,021	50,457,123	8,238,394	8,455,216	371,930,186

Criteria: 1. FEDES status is Active; 2. Excluding the following deficiencies: Unmet Supportable Space Needs(defic_code:6); Plant Management(9); Quarters(23);RP Inst Equip(24); Environmental Practices (EHS)(44); Environmental

3. Priority Year is between 0 and 3; 4. BLS Records are not Deleted nor Archived